EE 212 - Homework 12

Due April. 18, 2016

1. Problem 10.40

2. Problem 10.50

3. Construct the Bode plots of the following transfer function:

$$H(jw) = \frac{10(j\omega)^2}{(j\omega + 40)(j\omega + 200)}$$