EE 341 Fall 2005

EE 341 - Homework 13

Due November 30, 2005

For problems which require MATLAB, please include a MATLAB m-file which shows how you made your plots.

- 1. Problem 11.3 (a) (b) (c) (g) (h) (i)
- 2. Problem 11.4 (a) (c) (e)
- 3. Problem 11.9 (a) (b) (c) (d) (f). Hint: You can do (a) through (d) with the table of transforms and table of properties you do not need to do a partial fraction expansion.
- 4. Probelm 11.11 (a) (b) (c) (d) (e)